

CASES/HOLSTERS		
Image:	Holder, Heated, 24VDC (Not for use with display models)	11-0139
Image:	Holder, Heated, 36VDC (Not for use with display models)	11-0138
Image:	Holder, Heated, 48VDC (Not for use with display models)	11-0140
Image:	Holster, Universal, HLS-8000	HLS-P080
Image:	KIT,HOLSTER,SOFT/FORKLIFT, POWERSCAN	7-0519
Image:	Protective Case/Belt Holster, PC-8000 (for unit without display)	PC-P080
Image:	Protective Case/Belt Holster, PC-8000-D (for unit with display)	PCD-P080
Image:	Protective Case/Belt Holster, PC-9000	PC-P090

<b>MISCELLANEOUS</b>	
FIELDBUS CONVERTER, ETH IP, INDUSTRIAL	FBC9080-N200
FIELDBUS CONVERTER, PROFINET, INDUSTRIAL	FBC9080-N100
Star System USB Industrial Dongle 433 MHz	SD9030-433-A
Star System USB Industrial Dongle 910 MHz	SD9030-910-A

<b>MOUNTS/STANDS</b>		
Image:	Kit, Universal Mounting, PowerScan	11-0111