

Ultrasonic Fork/Label Sensors	
SRX3-5-US-3-M12-PNH = Ultrasonic Fork Clear Label Static teach with remote in PNP+NPN NO conn.M12	953171010
SRX3-5-US-M12-PNH = Ultrasonic Fork Clear Label Dynamic teach with remote in PNP+NPN NO conn.M12	953171000
SRX3-6-US-3-M8-PH = Ultrasonic Fork Clear Label Static teach with remote in PNP conn.M8	953171030
SRX3-6-US-3-M8-PN = Ultrasonic Fork Clear Label Static teach PNP+NPN NO conn. M8	953171050
SRX3-6-US-M8-PH = Ultrasonic Fork Clear Label Dynamic teach with remote in PNP conn.M8	953171020
SRX3-6-US-M8-PN = Ultrasonic Fork Clear Label Dynamic teach PNP+NPN NO conn.M8	953171040

CABLES	
CS-A1-03-G-03 = M12 5-p axial 3m	95ACC2110
CS-A1-03-G-05 = M12 5-p axial 5m	95ACC2120
CS-A1-03-G-10 = M12 5-p axial 10m	95ACC2140
CS-A1-03-U-03 = M12 5-p axial 3m UL 2464	95ASE1170
CS-A1-03-U-05 = M12 5-p axial 5m UL 2464	95ASE1180
CS-A1-03-U-10 = M12 5-p axial 10m UL 2464	95ASE1190
CS-B1-02-G-03 4 poli M8 3m grigio	95A251420
CS-B1-02-G-05 = M8 4-p axial 5m	95A251430
CS-B1-02-G-07 = M8 4-p axial 7m	95A251440
CS-B1-02-G-10 4 poli M8 10m grigio	95A251480
CS-B1-02-O-05 = M8 4-p axial 5m CEI 2034-01	95A251730
CS-B1-02-O-10 = M8 4-p axial 10m CEI 2034-01	95A251100
CS-B1-02-R-02 = M8 4-p axial 2m PUR	95A251620
CS-B1-02-R-05 = M8 4-p axial 5m PUR	95A251640
CS-B2-02-G-03 = M8 4-p radial 3m	95A251450
CS-B2-02-G-05 = M8 4-p radial 5m	95A251460
CS-B2-02-G-07 = M8 4-p radial 7m	95A251470
CS-B2-02-G-10 = M8 4-p radial 10m	95A251530
CS-B2-02-O-05 = M8 4-p radial 5m CEI 2034-01	95A251720

CS-B2-02-O-10 = M8 4-p radial 10m CEI 2034-01	95A251110
CS-B2-02-R-02 = M8 4-p radial 2m PUR	95A251630
CS-B2-02-R-05 = M8 4-p radial 5m PUR	95A251650